

SAFETY ALERT #97

Visual Inspection of New or Refurbished Rims

Date of Incident:

26th July 2014

What happened?

A Klinge TSP identified rim damage on a new rim.

Injury/Damage:

It was identified that the new rim had damaged stud holes.

Contributing Factors:

None known

Recommendations:

- It is important that all Klinge Tyre Service Personnel perform a thorough visual inspection of all rims, prior to them being fitted with tyres or fitted on machines even if they are new or refurbished.
- Tyre Service Personnel should not assume that new or refurbished rims are not without defect or damage.

Should you require anything further, please feel free to give me a call.

Eliminate All Unsafe Acts & Conditions.

Tanya Hoyle
Senior OHS & Compliance Advisor
Ph. 0448 030 166